



213 Hart Street
 Corner Hart Street & High Road
 1774
 Josiah Atwood (1740-1804) & Huldah

1935 Susqui-Centennial Celebration of the Town of Berlin – Berlin Old Houses.

About 1774 Atwood current owner: Charles Munson High Road


1985 Townwide Historic and Architectural Survey of Berlin, Connecticut. Survey # 052

1774 current owner: Hazel Munson 213 Hart Street

2018 Town of Berlin GIS Index.

Sketch

1774 current owner Walter & Jean Munson



Genealogy???

Josiah Atwood (1740-1804) married Huldah. They were members of the Kensington Congregational Church.

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM:	
QUAD:	
DISTRICT	IF NR, SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION	
1. BUILDING NAME (Common) <u>#052</u> (Historic)	
2. TOWN CITY <u>Berlin</u>	VILLAGE <u></u> COUNTY <u>Hartford</u>
3. STREET AND NUMBER (and/or location) <u>213 Hart Street</u> <u>8-3/53A/1</u>	
4. OWNER(S) <u>Munson, Hazel E. " " Kensington</u> <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private	
5. USE (Present) <u>Residence</u> (Historic) <u>Residence</u>	
6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No IF YES, EXPLAIN	
7. STYLE OF BUILDING <u>18th-century Vernacular</u> DATE OF CONSTRUCTION <u>c.1774</u>	
8. MATERIAL(S) (Indicate use or location when appropriate)	
<input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input checked="" type="checkbox"/> Fieldstone <u>foundation</u> <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input checked="" type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____	
9. STRUCTURAL SYSTEM	
<input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____	
10. ROOF (Type)	
<input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Ridge parallel to the street	
11. NUMBER OF STORIES <u>2 1/2</u> APPROXIMATE DIMENSIONS <u>34' x 19'</u>	
12. CONDITION (Structural) <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated (Exterior) <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated	
13. INTEGRITY (Location) <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved WHEN? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN <u>Little historic fabric visible</u>	
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES	
<input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) <u>On large lot, sloping southeast, overlooking pond</u> <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden	
15. SURROUNDING ENVIRONMENT	
<input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density	
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS <u>In a semi-rural area among scattered 19th- and 20th-century houses</u>	

DESCRIPTION

#52

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

This house displays little old or original exterior fabric. The ridge of the house runs east-west, parallel to Hart Street; to the rear (east), the lot slopes away steeply, exposing the original fieldstone foundation. The modern entry under a recent shelter is located in the right bay of the west elevation; to the left is a modern picture window; above are paired attic lights. All sash is recent. Original cornice detailing is obscured by modern siding. The north elevation has three recent windows and a recent brick chimney below the ridge of the roof. The south elevation has a cross-gable ell; the east elevation has a rear, framed-in, one-story bay extension.

18. ARCHITECT

BUILDER

19. HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Although it displays little original fabric (with the exception of the old or original fieldstone foundation), this house is significant as a surviving 18th-century house. Few original characteristics are visible from the exterior, but the scale and the ridge-parallel orientation reflect its early origin.

SOURCES

Bicentennial Papers.

PHOTO

PHOTOGRAPHER

HRC

DATE

11/84

VIEW

SE

NEGATIVE ON FILE

E25

COMPILED BY

Historic Resource Consultants

The Colt Armory

55 Van Dyke Avenue

Hartford, Connecticut 06108

DATE

12/84

20. SUBSEQUENT FIELD EVALUATIONS



21. THREATS TO BUILDING OR SITE

- ☒ None known ☐ Highways ☐ Vandalism ☐ Developers ☐ Other _____
- ☐ Renewal ☐ Private ☐ Deterioration ☐ Zoning ☐ Explanation _____